


Solution for the Mercedes 40pin Plug Compatibility with the AUX

Connector

Picture 1 – The original car interface

Picture 2 – The aftermarket unit's ISO wiring interface

The original car amplifier will have no sound if you directly plug the connector marked red.



Pic 1



Pic 2

It is required to alter the aftermarket units ISO interface by switching the direction of the AUX connector. You can do this as shown in the below pictures. Unclip the AUX connector, turn it around and slot it back into the ISO interface. Now you are ready to connect the cars interface to the ISO interface.

